Specimen Stage-Stretching Table
Heating and Drying Table



Instruction manual

12801, 13801, 14801, 15801, 17801, 12501, 13501, 14501, 15501 und 12895

1. Connect the power cable.
2. Power-switch “1” on. The control-lamp lights up.
3. Temperature-setting will be done by pressing SET – button and simultaneous pressing UP or DOWN – button. Stop pressing the UP or DOWN - button, when you read the desired temperature in the display.
4. The buttons UP or DOWN should always release before you stop the SET - button. The desired temperature can be read in the display while the SET - button will be pressed.
5. If you stop pressing the SET - button the measured temperature of the warming-plate will be displayed.

   The predialed temperature will be stored, even while the equipment is turned off.
6. Turn off only by using Power-switch “1”.

This equipment should not used in explosion-endangered areas.

MEDAX GmbH & Co. KG
Kieler Str. 211, D-24768 Rendsburg, Germany
Tel.: +49-(0)4331-136-870, Fax: +49-(0)4331-136-838
e-mail: info@MEDAX-Kiel.de
www.MEDAX-Kiel.de

Subject to technical change, Dec. 05

Spare Part List

Pos.	Description	Part-No.		
1	Power plug with integrated fuses	MEN 28100		
2	Fuse 2,5 A	MEN 11700		F 1 / F 2
	Fuse 4,0 A	MEN 12100	Only 14801 - 110 V	
3	Switch	MEN 10500		S 1 / H 1
4	Digital Controller	MEN 32000		DR 1
5	Thermometer probe	MEN 00200		R 1
6	Fuse of Temperature	MEN 01700		F 3
7	Condenser	MEN 25400		C 1
8	Heating Element		**for Type**	E 1
		MEN 14300	12501	
		MEN 07200	15501	
		MEN 06900	15801	
		MEN 06400	12801 / 12895	
		MEN 14900	17801	
		MEN 06500	13801 / 13501	
		MEN 06600	14801 / 14501	

Electrical Diagram